



Copied From original 'Pollard Syndrum' Service Notes
So there may be differences between this drawing
and the PCB

POLLARD SYNDRUM

REVISION 1 - 19/10/11

178 / 278 / 478

